

**SOUTH DELHI MUNICIPAL CORPORATION**

OFFICE OF THE EX. ENGINEER (M-3)/NGZ  
OPPOSITE KARGIL APARTMENT, SECTOR 12  
DWARKA, NEW DELHI-110078.

Email Address :- [eemiinajafgarh@gmail.com](mailto:eemiinajafgarh@gmail.com)



**दक्षिणी दिल्ली नगर निगम**

अधिशासी अभियंता(खंड-3)/नजफगढ़ क्षेत्र  
कारगिल अपार्टमेंट सेक्टर 12, द्वारका नई  
दिल्ली - 110078.

तीव्र पत्र :- [eemiinajafgarh@gmail.com](mailto:eemiinajafgarh@gmail.com)

No. D- 27 /EE-M-III/NGZ/2022-23

Dt. 07/04/2022

**STRUCTURAL STABILITY CERTIFICATE**

This is in reference to letter received in this office vide no. 02/F dated 05.04.2022 in which the Principal of Modern Convent School, Sector 04, Dwarka New Delhi-110078 has requested for issue of Structure Stability Certificate of the School Building.

As per the appearance & Structure Stability Certificate issued by Sh. Brijesh Kumar Singh, M.Tech.(Civil) Lic.No. SE-46 Sunrise Design Consortium, Architects, Engineers & Consultants S-03, Anshul Tower, Sector 04, Dwarka New Delhi-110078. School was inspected physically on 06.04.2022 by under signed along with JE. The building is found to be in good condition. The certificate has no concerned with the unauthorized construction in the school building premises & any other dispute regarding the title of the land.

This issues with prior approval from competent authority & is valid for the period of 03 years from the date of issue.

The Principal,  
Modern Convent School, Sector 04,  
Dwarka New Delhi-110078.

*Ajay*  
*07.04.2022*  
Asstt. Engineer(M-III)/NGZ

**AJAY KUMAR CHAUDHARY**  
AE/ (M-III)/ NGZ  
SOUTH DELHI MUNICIPAL CORPORATION